

---

## **CORE v1.00r3 Release Notes**

---

### **Version 1.00r3**

The following issues have been implemented in this release:

1. Fix problem with last speaker which, suddenly, reset alias and volume and alter the data of the rest speakers..
2. Fix problem SOLO mode was not canceled despite it was canceled through APP button.
3. Added KOREA Country Code as USA too.
4. Solved bug seldom a CUBE was identified as TUBE after a discover.
5. Improve internal communication.

### **Version 1.00r2**

The following issues have been implemented in this release:

6. Added support to update RF firmware to improve the system performance.
7. Added functionality WIS LED alternatively blink each 0.5s to indicate there are loudspeakers paired with different FW version than the CORE. This will cause bad performance.
8. Solved minor BUGs.

### **Version 1.00r1**

The following issues have been implemented in this release:

1. Bluetooth communication and performance has been improved.
2. Encoder Long Press action has been limited to avoid overloading the system.
3. Solved BUG set the HW MAC Address to all zeros after a factory default.

### **Version 1.00r0**

First release.

**WARNING:** In this version is not allowed to perform a FACTORY DEFAULT action. It will cause that the HW MAC Address turn into 00:00:00:00:00:00 and could cause a bad performance in the system.