




TEST REPORT CISPR 32, CISPR 35; IEC 61000-3-2; IEC 61000-3-3 EN 55032; EN 55035; EN 61000-3-2; EN 61000-3-3 Electromagnetic compatibility (EMC) Multimedia equipment Emission and immunity requirements	
Report Reference No.	200038851UDI-EMC
Compiled by (+ signature)	Mauro Sabidussi 
Approved by (+ signature).....	Marco Tell 
Date of issue	January 22, 2024
Total number of pages	57
Testing Laboratory	Intertek Italia S.p.A.
Address.....	Via Principe di Udine, 114 I - 33030 Campofornido (UD)
Applicant's name	NEEC AUDIO BARCELONA
Address.....	MOTORS, 166 08038 BARCELONA - SPAIN
Test specification:	
Standards.....	CISPR 32:2015 + AMD1, CISPR 35:2016, IEC 61000-3-2:2018 + AMD1, IEC 61000-3-3:2013 + AMD1+ AMD2 IEC EN 55032:2015 + AMD1 + AMD11, EN 55035:2017 + AMD11, EN IEC 61000-3-2:2019 + AMD1, EN 61000-3-3:2013 + AMD1 + AMD2
Test procedure	
Non-standard test method.....	N/A
Test Report Form No.	RT-EMEA-IT-EMC-014-IAS
TRF date.....	23 May 2019
Test item description	Digital audio manager
Trade Mark	
Manufacturer	NEEC AUDIO BARCELONA
Covered models.....	HADA4B150, HADA4B250, HADA4B400, HADA4B500, HADA4B750
Tested models	HADA4B150, HADA4B750
Ratings.....	HADA4B150: 80-265 V; 45-65 Hz; 70 W HADA4B750: 80-265 V; 45-65 Hz; 375 W
<p>This report is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this report. Only the Client is authorized to permit copying or distribution of this report and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this report are relevant only to the sample tested. This report by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.</p>	